



GUAM POWER AUTHORITY

ATURIDÁT ILEKTRESEDÁT GUÅHAN
P.O.BOX 2977 • HAGÁTÑA, GUAM U.S.A. 96932-2977

FOR IMMEDIATE RELEASE

FOR MORE INFORMATION
CONTACT: JOYCE SAYAMA
COMMUNICATIONS MANAGER
PHONE NO.: 671 648-3145

April 22, 2026

Power System Status Restoration

Day 6 Since COR4 – ST Sinlaku

(Fadian, Mangilao) – The Guam Power Authority (GPA) continues its power restoration process and have made progress to its post-typhoon recovery. In an effort to keep the public updated, we'll continue to provide a recovery summary that summarizes our restoration progress to the Island-Wide Power System (IWPS).

Impacts from ST Sinlaku - Recovery Summary

As of 9:00 a.m., Wednesday, April 22, 2026

IWPS	PERCENTAGES
System Load Restored	95%
GPA Feeders/Circuits Energized	100%

GENERATION CAPACITY	MW
Current Peak Demand <i>(Targeted Demand of 234 MW met)</i>	238

Notes: - All feeders are now energized; Crews continue to work on isolated areas.
- GPA has adequate generation capacity to support peak demand.

Feeders/Circuits: A total of 63 feeders/circuits are energized today of the 63 distribution feeders/circuits.

TODAY'S KEY OBJECTIVES INCLUDE:

- **All 63 feeders/circuits have now been restored.**
- During this stage of recovery, some energized feeders may still leave pockets of isolated customers with damages. Crews have been and continue to address the remaining isolated areas requiring more complex repairs and/or significant vegetation clearing.
- No one will be left behind. Crews have been working 12-16 hour shifts since the storm, through the day and night, for restoration efforts and will continue to work until all customers have been restored.
- As power lines heat up, weak points of the system will be apparent (*e.g., storm damaged transformers, fuse cutouts, lightning arrestors, connections*). Additionally, hardware components may have been loosened from the passing of the storm which may fail after power had been restored. Crews will do their best to make immediate repairs; if they cannot, they will return to make the repairs as soon as possible.
- Crews continue working on urgent needs across the island.

FOR CUSTOMERS WHO REMAIN WITHOUT POWER:

- In some areas, power may be restored to main lines while additional repairs are still needed on transformers, service lines, or customer connections.
- Customers may also be experiencing isolated damage that requires crews to return to address these additional repairs.
- If surrounding areas have power, customers may be part of a smaller outage pocket.
- Customers are asked to limit calls to the GPA Dispatch Center (PSCC) to critical issues such as downed power lines, blown transformers, low voltage conditions, or other situations that may present a safety concern. For additional assistance, customers may report these issues to GPA Customer Service via phone at (671) 648-5787/88/89, or via email at customersfirst@gpagwa.com.

GENERAL NOTIFICATIONS:

- Individuals with medical needs: Those requiring electrically powered life-support or oxygen tanks or similar devices should arrange to stay at an alternate location where electricity is available, such as a hospital or with family or friends who have power restored. Be prepared to bring your oxygen supplies, medical equipment, and medications with you.
- Personal use of generators: GPA asks that you ensure your main breakers are opened (off position) when operating your generator. This is for the safety of the crews and your equipment.
- Carbon monoxide safety hazard: It is a colorless, odorless gas that can cause serious illness or death. The risk increases during outages when generators or fuel-powered equipment are used improperly. Never use generators, grills, or portable stoves indoors. Keep equipment away from doors, windows, and vents, and never run vehicles inside garages. If you feel dizzy, nauseated, or lightheaded, move to fresh air immediately. If you suspect carbon monoxide exposure, call emergency services immediately.
- Voltage fluctuations during restoration: As power is restored, some customers may experience temporary voltage fluctuations such as flickering lights, dimming, or partial power. Customers are advised to shut off their main breaker and report the issue to GPA.
- Damaged Weatherheads and other Electrical Components: Customers are advised to conduct their own home and property assessment, including the weatherhead, meter box and other electrical components. If electrical equipment such as the weatherhead or meter box was damaged during the storm, it must be repaired before service can be restored. For more information, please contact GPA Customer Service at (671) 648-5787/88/89.
- Please stay away from all down lines and equipment as they may still be energized and can cause harm if you come in contact with the lines or equipment. Consider such situations as dangerous and life threatening. To report downed power lines, contact GPA Trouble Dispatch at (671) 475-1472/1473/1474. Customers may also email customersfirst@gpagwa.com or send a direct message on GPA's Facebook or Instagram page. Please provide the exact location or address, contact information and condition of location when submitting your report.

GPA thanks our customers for their patience and asks for their continued support as we work to bring our IWPS back to normal operations as quickly as possible.

To get the most up-to-date information, please visit our website at www.guampowerauthority.com and click on our [Post-Typhoon Sinlaku Restoration Updates](#) banner on our homepage or follow our official social media pages:

Facebook: <https://www.facebook.com/GuamPowerAuthority>

Instagram: <https://instagram.com/guampowerauthority>